Corner I.D. # 106T

## MONUMENT RECORD

## STATE OF INDIANA ~ COUNTY OF MONROE

8/23/2016, Rachel Savich Oser, Fbk. 48, pg. 47/25/2018, Cassidy Raley, Fbk. 52, pg. 22 Monument recovered flush with ground, apport the whole thing is crooked	+	been disturbed. Cap is still connected to rod,	•
	446	Q Traffic Signal Pole (S. Bolt)	4
	oć vi	Fire Hydrant (N. Bolt)	N N.T.S.
- p-		- T-	Aluminum Monument at Corner = 0

I, Matthew L. Cooper, here by certify that this document was prepared under my direction in accordance with the provisions of Section 17-3-64-4 through 17-3-64-8 of the Indiana Code, being Acts of 1965, Chapter 319; this 9th day of June, 2004 A.D.

Indiana Registered Land Surveyor No. LS20200079

COMPLETED By Sturies

No.LS20200079



200 Feet 50 100 ImageSource: 2014 Monroe County Pictometry



Office of the Monroe County Surveyor 2004 Geodetic Control Project 119 West 7th Street Bloomington, Indiana 47404 (812) 349-2570





